



www.minispares.com  
info@minispares.com

tel: 01707 607 700  
fax: 01707 656 786

See our website for 24 hour shopping and technical advice.

## **C-AEG579**

### **HI-GRADE CAM FOLLOWER**

Re-developed to combine all the attributes of previous followers of this quality, plus unique push rod location. Much of the valve train problems suffered by the A-series engine is caused by the little known about problem of the push rods being able to float/jump about in the follower. To minimise the problem, we've taken great care to ensure consistent and accurate tolerances of the push rod socket in the follower base, maximising push rod location and valve train accuracy and control. Extreme attention to detail and tolerances ensures consistent edge chamfering and foot curvature. The built-in extra height increases follower stability, and careful paring down of dimensions keeps weight to a minimum. Both greatly improve follower life. Suitable for all cam types and uses.